



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1005
Issue Date 08-15-01

Issue: Display does not light when switched on in low ambient light.

Affected Models: GPH5992X Dash mount models serial number less than 0112000.

Recommended Action: Run utility program available from RELM.com.

Parts and Equipment Requirements:

- 1- LAA0725 Programming Cable
- 1- Software Patch from RELM.com

Procedure:

1. Download and run patch from BK Radio service site
<http://www.relm.com/Utility/>

Please note that the software will validate the software revision level within the unit before writing patch. The patch will only be written if the unit requires it.