



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1007
Issue Date 09-12-01

Issue: 1. Momentary superfluous display at power up.
2. Potential of the microprocessor memory corruption.

Affected Models: GMH5992X and GMH2992R Dash and Remote mount models with serial numbers below 0137001.

Recommended Action: Run utility program available from RELM.com.

Comments: This utility patch writes information to both the control head and radio core.

Parts and Equipment Requirements:

- 1- LAA0725 Programming Cable
- 1- Software Patch from RELM.com

Procedure:

1. Download and run patch from BK Radio service site
<http://www.relm.com/Utility/>

Please note that this software will validate the firmware revision level within the unit before writing patch. The patch will only be written if the unit requires it.