



7100 Technology Drive  
West Melbourne, FL 32904  
1-800-422-6281

# Service Bulletin

BKSB-1049  
Issue Date 6/7/2017



**Issue:** Update – Firmware (Ver. 5.5.0c)

**Importance:** Recommended but not required

**Affected Models:** KNG-Pxxx, KNG2-Pxxx, KNG-Mxxx, KAA0660, and KAA0670

**Recommended Action:** Update as required. The features and fixes are listed below.

**NOTE: THIS BULLETIN DOES NOT APPLY TO KNG-S MODELS**

## Bug Fixes

### General:

- Fixed cloning of zones and picklist from 5.5.x to older/legacy firmware  
(Refer to Service Bulletin [BKSB-1050](#) for further cloning information)
- Set Bluetooth discoverable to off by default
- Fixed to support AINA BT speaker-mic

(NOTE: Refer to Service Bulletin [BKSB-1051](#) for important compatibility details for this update)

## Radio Firmware Update

### Parts and Equipment Requirements:

- 1- KAA0710 Programming Cable
- 1- Firmware Update from BKTECHNOLOGIES.com

### Procedure:

- 1) Verify the radio firmware revision installed in your KNG.  
Select “Versions” from the radio menu.  
Update radios whose software version is less than 5.5.0c.
- 2) Download and install the KNG Field Update 5.5.0c for your portable, mobile, remote mount control head or handheld control head from the support section of the [www.bktechnologies.com](http://www.bktechnologies.com).

Shortcut: [http://www.relmservice.com/products/BK\\_Digital.asp](http://www.relmservice.com/products/BK_Digital.asp)