



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1050
Issue Date 6/7/2017



Issue: Destination clone errors with firmware 5.5.0 and older

Importance: Resolves clone errors with older firmware

Affected Models: KNG-Pxxx, KNG2-Pxxx, KNG-Mxxx

Recommended Action: Follow cloning instructions listed below.

NOTE: THIS BULLETIN DOES NOT APPLY TO KNG-S MODELS

Cloning Bulletin

When cloning to and from radios with firmware older than 5.5.0 it is recommended to have both radios fully powered on for approximately 30 seconds before attempting to clone. This recommendation helps to avoid destination clone errors with older firmware.