



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1055
Issue Date 6/18/2018

Issue: Firmware Update (Ver. 5.6.0a) and PC Radio Editor (KAA0733-Ver. 5.6.0)

Importance: Recommended, but not required

Affected Models: KNG-Pxxx, KNG-Mxxx, KAA0660, and KAA0670 with firmware and Radio Editors prior to versions listed above.

Recommended Action: Update as required. The features and fixes are listed below.

NOTE: THIS BULLETIN DOES NOT APPLY TO KNG-S MODELS

Firmware 5.6.0a radio features and bug fixes:

Click [here](#) to see the updated features and bug fixes.

Please read the following [Technical Service Bulletin](#) before updating to 5.6.0a firmware.

Firmware Update

Parts and Equipment Requirements:

- 1- KAA0710 Programming Cable
- 1- Firmware Update from BK Technologies

Procedure:

- 1) Verify the radio firmware revision installed in your KNG.
Select "Versions" from the radio menu.
Update radios whose firmware version is 5.6.0 or less.
- 2) [Download](#) and install the KNG Field Update 5.6.0a All In one file for your portable, mobile, remote mount control head or handheld control head.

Software Editor RES 5.6.0 radio features and bug fixes:

Click [here](#) to see the updated features and bug fixes.

Please read the following [Technical Service Bulletin](#) before updating to 5.6.0 software editor.



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1055
Issue Date 6/18/2018

Software Update

Customers with a registered copy of the radio editor can download the latest release from the service section of BK Technologies Website by entering a valid serial number on the Software Update page. <http://www.relmservice.com/software/update.asp>

Authorized customers can download the updated version by logging in prior to navigating to the software section of the website.

The latest revision may also available be purchased from your BK Technologies dealer or directly from BK Technologies at (800) 821-2900