



7100 Technology Drive
West Melbourne, FL 32904
1-800-422-6281

Service Bulletin

BKSB-1043
Issue Date 7/29/2016



Issue: KNG to KNG cloning incompatibility

Importance: For informational purpose

Affected Models: KNG Series

Recommended Action: As needed.

When cloning to KNG to KNG Series, it is important that both radios have the same revision firmware. Ungoverned results may occur due to possible parameter differences between the two different firmware versions.

Also when updating the firmware, please read the release notes as it will reference the compatible version NeoVision (radio editor) required to be used for the firmware version that is being released.